VOL. VIII. INDEX.

	Quarterly No.	Page No.
A		
Automatic Sprinklers, Annual Summary	4	435
B		
Barium Dioxide	1	88
Blower Torch Installation	4	376
Building Heights, Regulating	2	176
Bureau of Standards, The U. S.	3	266
C		
Chapters, The: No. 1, Page 14; No. 2, Page 142; No. 3, Page 251	4	347
Chimney, Typical Carelessness with	2	148
Collapsed Floors from Overloading	4	358
Committee Meetings	3	256
Conflagrations, Debarment of City	1	21
Cotton Mills—Fire Record	1	92
D		
Decarbonizing Cylinders of Automobile Motors	4	364
Dry Cleaning Establishment Fire	1	34
Dry Valves, Field Tests of	2	203
Dust Explosions and Static Electricity in Mills and Elevators	4	412
E		
Editorial: No. 1, Page 5; No. 2, Page 133; No. 3, Page 245	4	341
Executive Committee Meeting	1	16
F		
Fence, The Wooden	3	263
Firecrackers, The Fire Hazard of	4	362
Fireproofing Course, Department of Civil Engineering, University of California	1	19
Fire Causes: No. 1, Page 120; No. 2, Page 233	4	428
Fire Department Civil Service Examinations	2	159
Fire Drill Instructions	3	336
Fire Door, Killed by	2	200

VOL. VIII. INDEX.

	Quarterly No.	Page No.
A		
Automatic Sprinklers, Annual Summary	4	435
B		
Barium Dioxide	1	88
Blower Torch Installation	4	376
Building Heights, Regulating	2	176
Bureau of Standards, The U. S.	3	266
C		
Chapters, The: No. 1, Page 14; No. 2, Page 142; No. 3, Page 251	4	347
Chimney, Typical Carelessness with	2	148
Collapsed Floors from Overloading	4	358
Committee Meetings	3	256
Conflagrations, Debarment of City	1	21
Cotton Mills—Fire Record	1	92
D		
Decarbonizing Cylinders of Automobile Motors	4	364
Dry Cleaning Establishment Fire	1	34
Dry Valves, Field Tests of	2	203
Dust Explosions and Static Electricity in Mills and Elevators	4	412
E		
Editorial: No. 1, Page 5; No. 2, Page 133; No. 3, Page 245	4	341
Executive Committee Meeting	1	16
F		
Fence, The Wooden	3	263
Firecrackers, The Fire Hazard of	4	362
Fireproofing Course, Department of Civil Engineering, University of California	1	19
Fire Causes: No. 1, Page 120; No. 2, Page 233	4	428
Fire Department Civil Service Examinations	2	159
Fire Drill Instructions	3	336
Fire Door, Killed by	2	200

	Quarterly No.	Page No.
Fire Loss in United States and Canada, 1914	3	260
Fire Prevention Questions for School Children	2	147
Forest Fire Loss in 1914, National	4	351
G		
Gasoline Fires Caused by Frictional Electricity	2	152
General Fire Record: No. 1, Page 109; No. 2, Page 217; No. 3, Page 320	4	415
H		
Hose Streams on High Tension Wires	2	153
I		
Individual Responsibility for Fires	3	283
L		
Laundries — Fire Record	2	208
Laundries, Steam	4	383
Life, Fires in Which There Was Loss of: No. 2, Page 224	3	328
M		
Mechanical Defects as Fire Causes	1	35
Members' Activities: No. 2, Page 144; No. 3, Page 253	4	349
Mexican Crude Rubber Company (Fire)	3	329
Motion Picture Film Hazards	4	367
Motion Pictures in Fire Protection	4	352
Mrs. O'Leary and Her Cow	2	146
O		
Openings, The Treatment of Vertical and Horizontal	3	273
Oxy-Acetylene Gas Explosion	3	297
P		
Paper Mills — Fire Record	3	303
Points of Interest from Fire Reports: No. 1, Page 116; No. 2, Page 230	4	423
Printer's Safety Cabinet	3	281
R		
Roofs, Wooden on Fire-resistive Buildings	2	149
Rubber Boot and Shoe Factories, Their Processes and Hazards	1	41
Rubber Coated Fabrics	1	59

	Quarterly No.	Page No.
S		
Safe Grounding for Fire and Police Signal Boxes	3	278
Seattle Invites Her Fate	4	359
Spontaneous Combustion in Burlap	2	202
Sprinkler Fire Tables, Annual	4	435
Storing and Handling Stocks on Skids	4	377
T		
Tanks, Collapsing Water	1	85
Tanks, Elevated	1	65
Turbo-Generators, Fire Hazard in	4	379
U		
Unit System of Wood Floor Surface for Fireproof Manufacturing Buildings	1	38
V		
Volunteer Fire Departments	4	387